

# ABS Quality Evaluations

## Certificate Of Conformance

This is to certify that the Quality Management System of:

**Mistras Services**

**MW Regional Office #496/596**

**161 Tower Drive, Suite E  
Burr Ridge, IL 60527  
U.S.A.**

(WITH ADDITIONAL FACILITIES LISTED ON ATTACHED ANNEX)

has been assessed by ABS Quality Evaluations, Inc. and found to be in conformance with the requirements set forth by:


**ISO 9001:2015**

The Quality Management System is applicable to:

**MATERIALS TESTING SERVICES**

This certificate may be found on the ABS QE Website ([www.abs-qe.com](http://www.abs-qe.com)). For certificates issued in the People's Republic of China information may also be verified on the CNCA website ([www.cnca.gov.cn](http://www.cnca.gov.cn)).

Certificate No: 43749  
Certification Date: 12 August 2019  
Effective Date: 12 July 2022  
Expiration Date: 12 July 2025  
Revision Date: 13 July 2022



Dominic Townsend, President



Validity of this certificate is based on the successful completion of the periodic surveillance audits of the management system defined by the above scope and is contingent upon prompt, written notification to ABS Quality Evaluations, Inc. of significant changes to the management system or components thereof.

ABS Quality Evaluations, Inc. 1701 City Plaza Drive, Spring, TX 77389, U.S.A.  
Validity of this certificate may be confirmed at [www.abs-qe.com/cert\\_validation](http://www.abs-qe.com/cert_validation).

# ABS Quality Evaluations

ISO 9001:2015  
**Certificate Of Conformance**  
**ANNEX**

Certificate No: 43749

## Mistras Services

At Below Facilities:

Facility: 161 Tower Drive, Suite E  
Burr Ridge, IL 60527  
U.S.A.

Activity: Management of QMS. Materials testing services; administrative support

Facility: East Granby #582  
16F International Drive  
East Granby, CT 06026  
U.S.A.

Activity: Materials testing services

Facility: La Porte, TX  
4000 Underwood Road  
La Porte, TX 77571  
U.S.A.

Activity: Materials testing services

Facility: MTN Region Office #592  
4117 S. Valley Drive Unit 100  
Longmont, CO 80504  
U.S.A.

Activity: Materials testing services

Facility: NE Region Office #494/594  
5 Nealy Boulevard  
Trainer, PA 19061  
U.S.A.

Activity: Materials testing services

Facility: San Francisco  
6170 Egret Court  
Benicia, CA 94510  
U.S.A.

Activity: Materials testing services



Validity of this certificate may be confirmed at [www.abs-qe.com/cert\\_validation](http://www.abs-qe.com/cert_validation).

# ABS Quality Evaluations

ISO 9001:2015  
**Certificate Of Conformance**  
**ANNEX**

Certificate No: 43749

## Mistras Services

At Below Facilities:

Facility: Mistras Canada Inc.  
8109 Edgar Industrial Drive  
Red Deer, AB T4P 3R2  
Canada

Activity: Materials testing services

Facility: Western Region Office #585  
1201 Francisco Street  
Torrance, CA 80502  
U.S.A.

Activity: Materials testing services

Facility: Boston #581  
2 Millbury Street  
Auburn, MA 01501  
U.S.A.

Activity: Materials testing services



Validity of this certificate may be confirmed at [www.abs-qe.com/cert\\_validation](http://www.abs-qe.com/cert_validation).

# ABS Quality Evaluations

## Certificate Of Conformance

This is to certify that the Environment Management System of:

**Mistras Services**

**Northeast Regional Office #494/594**

**5 Nealy Boulevard  
Trainer, PA 19061  
U.S.A.**

has been assessed by ABS Quality Evaluations, Inc. and found to be in conformance with the requirements set forth by:


**ISO 14001:2015**

The Environment Management System is applicable to:

**MATERIALS TESTING SERVICES**

This certificate may be found on the ABS QE Website ([www.abs-qe.com](http://www.abs-qe.com)). For certificates issued in the People's Republic of China information may also be verified on the CNCA website ([www.cnca.gov.cn](http://www.cnca.gov.cn)).

Certificate No:	43750
Certification Date:	17 March 2015
Effective Date:	04 March 2021
Expiration Date:	11 March 2024
Revision Date:	04 March 2021



Dominic Townsend, President



Validity of this certificate is based on the successful completion of the periodic surveillance audits of the management system defined by the above scope and is contingent upon prompt, written notification to ABS Quality Evaluations, Inc. of significant changes to the management system or components thereof.

ABS Quality Evaluations, Inc. 1701 City Plaza Drive, Spring, TX 77389, U.S.A.  
Validity of this certificate may be confirmed at [www.abs-qe.com/cert\\_validation](http://www.abs-qe.com/cert_validation).

# ABS Quality Evaluations

## Certificate Of Conformance

This is to certify that the Environmental Management System of:

**Mistras Services**

**Northeast Regional Office #494/594**

**5 Nealy Boulevard  
Trainer, PA 19061  
U.S.A.**

has been assessed by ABS Quality Evaluations, Inc. and found to be in conformance with the requirements set forth by:

**ISO 14001:2015**

The Environmental Management System is applicable to:

**MATERIALS TESTING SERVICES**



This certificate may be found on the ABS QE Website ([www.abs-qe.com](http://www.abs-qe.com)). For certificates issued in the People's Republic of China information may also be verified on the CNCA website ([www.cnca.gov.cn](http://www.cnca.gov.cn)).

Certificate No:	43750
Certification Date:	17 March 2015
Effective Date:	26 January 2024
Expiration Date:	11 March 2027
Revision Date:	26 January 2024

Dominic Townsend, President



Validity of this certificate is based on the successful completion of the periodic surveillance audits of the management system defined by the above scope and is contingent upon prompt, written notification to ABS Quality Evaluations, Inc. of significant changes to the management system or components thereof.

ABS Quality Evaluations, Inc. 1701 City Plaza Drive, Spring, TX 77389, U.S.A.  
Validity of this certificate may be confirmed at [www.abs-qe.com/cert\\_validation](http://www.abs-qe.com/cert_validation).